

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018

**Grave Peak Lookout
Site 10IH575
Site Photographs
Lochsa/Powell Ranger District
Nez Perce - Clearwater National Forest
Idaho County, Idaho**



Photo 18-212
Grave Peak Lookout. North elevation.
Direction: south



Photo 18-213
North elevation.
Direction: south

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-214
Door on south elevation.
Direction: north

Photo 18-215
Close-up of cupola, south
elevation.
Direction: north



Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-216
Wood cabinet on lookout
interior.
Direction: NA



Photo 18-217
Looking at door and opening on the
south elevation. Photo taken from inside
the lookout.
Direction: south

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018




Photo 18-218
Poor condition of the two layers of
hardwood floor near the door.
Direction: NA



Photo 18-219
Looking up at the roof of the cupola from within
the lookout.
Direction : NA

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-220
Looking at chimney, roof flashing and
lightning protection from roof.
Direction: NA



Photo 18-221
Close-up view of
shiplap siding.
Direction : NA

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-222
Close-up of
window
shutters built
in 1998.
Direction: NA



Photo 18-223
Close-up of door
threshold.
Direction: NA

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-224
This appears to be an original window shutter
that was left laying on the ground.
Direction: NA



Photo 18-225
Close-up view of broken window glass.
Direction: NA

Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-226
View of floor joists
and deteriorated
subfloor. Photograph
taken from under
building.
Direction: NA

Photo 18-227
View of floor joists and
subfloor. Photograph
taken from under
building.
Direction: NA



Grave Peak Lookout
Site 10IH575
Photographs taken on 10/1/2018



Photo 18-228
Interior view of lookout and wood stove.
Direction: NA